



Spare Parts/ Ersatzteile/Pièces de rechange/Pezzi di ricambio/Piezas de requesto/Parte de reposição/Reserveonderdelen/Reservdelar/Reservedeler/Varaosat/Vraosat/Varahlutir Ανταλλακτικά/Yedek parçalar/Náhradní díly/Náhradné diely/Nadomestni deli/Резервни части/Запчасти/Części zapasowe/Piese de schimb/Rendelhető alkatrészek/ Запасні частини/ Резервни делови/Резервни делови/Резервни делови/Atsarginių dalių/Tellitavad varuosad/Rezervju daļu

XX = AA, AD ...


- | | |
|-----------------------|------------------|
| 1. A 961 105 XX | 29. A 960 333 XX |
| 2. A 961 104 XX | 30. A 961 820 XX |
| 3. A 961 011 XX | 31. A 961 126 XX |
| 4. A 961 077 XX | 32. A 961 124 NU |
| 6. A 961 798 NU | 33. A 961 095 NU |
| 7. A 963 299 NU | 34. A 963 574 NU |
| 9. A 961 194 NU | 35. A 961 094 NU |
| 10. A 961 220 NU | 36. A 961 097 NU |
| 11. A 961 013 XX | 37. A 961 090 NU |
| 12. A 961 227 NU | 38. A 960 483 XX |
| 14. A 961 337 NU (2x) | 39. A 961 178 XX |
| 15. A 961 088 NU | 40. A 960 026 XX |
| 16. A 961 087 NU | |
| 19. A 961 810 NU | |
| 20. A 963 330 NU | |
| 21. A 961 097 NU (2x) | |
| 22. A 961 014 NU | |
| 23. A 961 125 NU (3x) | |
| 24. A 961 017 NU (3x) | |
| 28. A 961 024 NU (2x) | |




Ideal Standard

MOMENTS
A 3917 ..., A 3913 ...


0506 / A 865 620
Made in Europe




A 3917





A 3913



Ideal Standard
Roentgenstrasse 9
54516 Wittlich
Germany





P	bar	MAX. 10	5		Q (3 bar)
T	°C	MAX. 80	50 40		l/min 20,5

